




# **XpandR™ Swaging/Tube Expander Tool**













### 175-EX REPLACEMENT PARTS LIST

175EXP XpandR Pliers 175EXC **XpandR** Case 3/8" head 175EX06 175EX08 1/2" head 5/8" head 175EX10 175FX12 3/4" head 175EX14 7/8" head ADDITIONAL SIZES AVAILABLE 175EX16 1" head 175EX18 1-1/8" head 175EX22 1-3/8" head 1-5/8" head 175EX26

! WARNING Keep body parts away from pinch/swage areas while using. Ensure tubing is secure in tool before swaging. Always wear approved eye protection. Broken materials may fly.



30333 Emerald Valley Parkway • Glenwillow, Ohio 44139 USA www.imperial-tools.com • info@stridetool.com

### **INSTRUCTIONS FOR USE**

- 1. Deburr inside of tube.
- 2. To create perfectly centered capillary sockets for soldering or brazing, you must use soft copper or a tube end that has been fully annealed.
- 3. Pull XpandR handle up to 90-degree position. Maintain this position as you thread the appropriate size head over the center-punch and tighten.
- 4. Insert the tube end over the XpandR head.
- 5. Pull the lever completely down.
- 6. Return the lever to the 90-degree position. Remove expanded tube.

©2016 Stride Tool, LLC. Made in France. This Imperial product is engineered and quality tested in the USA.


# To re-round slightly deformed tube ends

- Insert deformed tube end to the first groove of head
- Pull the lever completely down
- Return lever to the 90-day position
- Removed expanded tube

# **XpandR™ Swaging/Tube Expander Tool**










tube ends



To re-round slightly deformed

Insert deformed tube end to the

Pull the lever completely down

Return lever to the 90-day posi-

first groove of head

Removed expanded tube



## 175-EX REPLACEMENT PARTS LIST

10000772 B

175EXP XpandR Pliers 175EXC **XpandR** Case 3/8" head 175EX06 175EX08 1/2" head 175EX10 5/8" head 175EX12 3/4" head 7/8" head 175EX14 ADDITIONAL SIZES AVAILABLE 1" head 175EX16 175EX18 1-1/8" head 175EX22 1-3/8" head 175EX26 1-5/8" head

! WARNING Keep body parts away from pinch/swage areas while using. Ensure tubing is secure in tool before swaging. Always wear approved eye protection. Broken materials may fly.



30333 Emerald Valley Parkway • Glenwillow, Ohio 44139 USA www.imperial-tools.com • info@stridetool.com

### **INSTRUCTIONS FOR USE**

- 1. Deburr inside of tube.
- 2. To create perfectly centered capillary sockets for soldering or brazing, you must use soft copper or a tube end that has been fully annealed.
- 3. Pull XpandR handle up to 90-degree position. Maintain this position as you thread the appropriate size head over the center-punch and tighten.
- 4. Insert the tube end over the XpandR head.
- 5. Pull the lever completely down.
- 6. Return the lever to the 90-degree position. Remove expanded tube.

©2016 Stride Tool, LLC. Made in France. This Imperial product is engineered and quality tested in the USA.